


1/2" SQ. DR. SUPER DUTY IMPACT WRENCH



1496

| INDEX NO. | DESCRIPTION | REQ'D NO. | INDEX NO. | DESCRIPTION | REQ'D NO. |
|-----------|--|-----------|-----------|---|-----------|
| ★ 1 | Motor Housing Assembly (incl.2.25) | 1 | 23 | Air Inlet | 1 |
| ● 2 | Bushing | 1 | 24 | Grease Fitting | 1 |
| 3 | Valve Stem | 1 | ● 25 | Bushing | 1 |
| 4 | Throttle Valve | 1 | 26 | Socket Retainer | 1 |
| 4-1 | O-Ring | 1 | 27 | O-Ring | 1 |
| 5 | Reverse Valve | 1 | 28 | Standard Anvil | 1 |
| 6 | Steel Ball | 2 | 29 | Hammer Frame | 1 |
| 7 | Spring | 1 | 30 | Hammer Pin | 2 |
| 8 | O-Ring | 1 | 31 | Hammer | 1 |
| 9 | Reverse Knob | 1 | 32 | Ball Bearing | 1 |
| 10 | Regulating Valve | 1 | 33 | Front End Plate | 1 |
| 11 | Spring | 1 | 34 | Spring Pin | 1 |
| 12 | Trigger | 1 | 35 | Rotor Blade | 6 |
| 13 | Spring Pin | 1 | 36 | Rotor | 1 |
| 14 | Pin | 1 | 37 | Cylinder | 1 |
| 15 | Spring Pin | 1 | 37-1 | Spring Pin | 1 |
| 16 | O-Ring | 1 | 38 | Rear End Plate | 1 |
| 17 | Throttle Valve Seat | 1 | 39 | Ball Bearing | 1 |
| ★ 18 | Throttle Valve Assembly (incl.18-1.18-2) | 1 | 40 | Gasket | 1 |
| ● 18-1 | Throttle Valve | 1 | 41 | Backhead | 1 |
| ● 18-2 | Throttle Valve Pin | 1 | 42 | Screw | 4 |
| 19 | Exhaust Deflector | 1 | 43 | Rubber Grip | 1 |
| 20 | Spring | 1 | 44 | Muffler Element | 1 |
| 21 | O-Ring | 1 | 45 | Rubber Grip (Option) | 1 |
| 22 | O-Ring | 1 | TK | Tune-Up Kit { incl.4-1.6.7.8.11.21.22.26.27.35 (6).40 } | |

★ Must be Purchased in Assembly Set

● Recommended not to be purchased alone due to assembly difficulty

20180719R1